

VEHICLE INSPECTION REPORT

WN69YNA

Mercedes-Benz Sprinter 314 CDI

Inspection		Vehicle			
Serious Damage?	No	VAT	Plus VAT		
		V5	Buyer To Apply		
Details					
Reg. date	31/12/2019	Colour	WHITE	CAP Clean	£7,600.00
Year	2019	VIN	WDB9071352N039587	CAP Average	£6,675.00
Mileage	125,424 Miles Not Warranted	Body Style	Dropside L3	CAP Below	£5,325.00
		MOT Due	05/09/2025	Gearbox	MANUAL
Fuel Type	Diesel	_			
AD BLUE					
Tyres NSF					
NSR					
OSF					
OSR					
Spare	-		-	-	-

Features

Front electric windows

Photos

















Condition Check



Damage Photos



1: Screen Front Chipped Over 10mm



2: Bumper Front Moulding Scuffed (Unpainted) UpTo 100mm



3: Bumper Front Moulding Scuffed (Unpainted) UpTo 100mm



4: Bonnet Dented 2 Or Less UpTo 10mm



5: Wing nsf Dented With Paint Damage



6: Door Mirror Assy nsf Scuffed (Unpainted) UpTo 100mm




7: Flasher Side Repeater ns Broken Replace



8: Other N/A N/A



9: Other N/A N/A



10: Door Mirror Assy osf Scuffed (Unpainted) UpTo 100mm



11: Door osf Chipped 1 To 5

Interior

Carpet Condition Seat Condition	Average Average		Upholstery Condition Odour	Average No	
Engine Runs		OK	Gearbox 1st and Reverse	Test	OK
Brakes		OK	Clutch Slip Test from Stati	ic	OK
Parking Brake		OK	Gearbox Static Gear Sele	ction (engine running)	OK
			No Excessive Smoking		OK
EML light illuminated		OK	Oil warning light illuminate	ed	OK
Airbag light illuminated		OK	DPF light illuminated		OK
ABS light illuminated		OK	Service indicator light illun	ninated	OK