

VEHICLE INSPECTION REPORT

KN72YZB

Mercedes-Benz Sprinter 315 CDI Premium

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 03/10/2022

Year 2022

Mileage 10,633 Miles
Warranted

Fuel Type Diesel

Colour WHITE

VIN W1V9106332P498716

Body Style Panel Van L2

MOT Due 03/11/2026

CAP Clean £20,500.00

CAP Average £19,000.00

CAP Below £16,350.00

Gearbox MANUAL

Gears 6

SIDE LOAD DOOR

Tyres

NSF

NSR

OSF

OSR



Spare

Features

- Bluetooth connection
- Digital radio
- Passenger airbag
- Cruise control
- Air conditioning
- Central locking
- Front parking sensor
- Front electric windows
- Cloth seat trim
- Rear parking sensor
- Drivers airbag


Photos







Condition Check



Damage Photos



1: Qtr Panel nsr
Dented
Over 30mm



2: Qtr Panel Moulding ns
Scuffed (Unpainted)
Over 100mm



3: Qtr Panel nsr
 Scratched
 Over 25mm Not Thru Paint



4: Door nsr
 Chipped
 Over 5mm

Interior

Carpet Condition		OK	Upholstery Condition		OK
Seat Condition		OK	Odour		No
Engine Runs	OK		No Excessive Smoking		OK
EML light illuminated	OK		DPF light illuminated		OK
ABS light illuminated	OK				