

VEHICLE INSPECTION REPORT

BF23YPN

Iveco Eurocargo 120-210

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Location	Doncaster	GVW	12000kg	MOT Due	Expired
Reg. date	30/08/2023	Colour	WHITE	Cab Type	DAY CAB
Year	2023	VIN	ZCFAH1EF702729531	Gearbox	MANUAL
Mileage	53,149 Km Warranted	Body Style	Pole Erection Unit	Axle Combi	4x2
Fuel Type	Diesel	Service history	Yes	Rear Suspension	Steel

PALFINGER PK9.501 (2 EXT) REMOTE CRANE (YEAR 2022), AUTOGUIDE AUGER, POLE JACK, HEATED DRYING LOCKER, 240V POWER

Tyres

NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features

- Bluetooth connection
- Air conditioning
- Cruise control
- Front electric windows
- Park assist camera
- Central locking
- Digital radio
- Cloth seat trim


Photos







Condition Check



Damage Photos



1: Door Mirror Assy osf
Scuffed (Unpainted)
UpTo 100mm



2: Bonnet
Chipped
Multiple Chips



3: Bumper Front Moulding
Missing
Replace

4: Door Mirror Assy nsf
Scuffed (Unpainted)
Over 100mm



5: Panel Front
Scratched
Over 25mm Not Thru Paint

6: Door nsf
Scratched
Over 25mm Thru Paint



7: Door osf
Chipped
Multiple Chips

8: Screen Front
Chipped
Over 10mm



9: Seat Base Cover osf
Soiled
Heavy

10: Seat Base Cover nsf
Soiled
Heavy

Interior

Carpet Condition		OK	Upholstery Condition		OK
Seat Condition		Poor	Odour		-
Engine Runs		OK	No Excessive Smoking		OK
EML light illuminated		OK	DPF light illuminated		OK
ABS light illuminated		OK			